

GCA

**PATENT** 

### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:	)
Nobushige KORENAGA	Examiner: D. Le
Application No.: 10/716,702	: ) Group Art Unit: 2834
Filed: November 20, 2003	;
For: STAGE APPARATUS AND METHOD OF CONTROLLING THE SAME	: ) December 13, 2005 :
U.S. Patent No. 6,946,757 B2	) :
Issued: September 20, 2005	Certificate
	DEC 1 5 2005
The Commissioner for Patents P.O. Box 1450	of Correction
Alexandria, VA 22313-1450	

## REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

Patentee requests that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of U.S. Patent and Trademark Office mistakes and mistakes of a minor nature which are not the fault of the U.S. Patent and Trademark Office.

01/4/2005 SZESDIE1 00000010 6946757 01 F0:1811

100.00 gp

**Attention: Certificate of Correction Branch** 

- 1 -

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction. Any additional fee required by this paper may be charged to Deposit Account No. 06-1205.

Patentee's undersigned attorney may be reached in our Washington, D.C. Office by telephone at (202) 530-1010. All correspondence should continue to be directed to our below-listed address.

Respectfully submitted,

Attorney for Patentee Steven E. Warner

Registration No. 33,326

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

SEW/eab

DC\_MAIN 224888v1

PRINTER'S TRIM LINE

Staple Here Only!

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.: 6,946,757 B2

: September 20, 2005 DATED

INVENTOR(S): Nobushige KORENAGA

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### ON THE COVER PAGE:

In item "(56) References Cited," under "U.S. PATENT DOCUMENTS," the eighthlisted patent, "5,841,250 A 11/1998 Korenage et al. ......318/135" should read -- 5,841,250 A 11/1998 Korenaga et al. ...... 318/135 --

### COLUMN 2:

Line 66, "m<sub>1</sub>, is" should read -- m<sub>1</sub> is --.

### COLUMN 4:

Line 47, "FIGS. 18" should read -- FIG. 18 --.

#### **COLUMN 8:**

Line 60, "acceleration a," should read -- acceleration  $\alpha$ , --. Line 65, "acceleration a," should read -- acceleration  $\alpha$ , --.

MAILING ADDRESS OF SENDER:

PATENT NO. <u>6,946,757 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82)

No. of add'l. copies @ 30¢ per page



PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE

# CERTIFICATE OF CORRECTION

PATENT NO.: 6,946,757 B2

DATED: September 20, 2005

INVENTOR(S): Nobushige KORENAGA Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### COLUMN 9:

Line 35, "Y bar 21 1," should read -- Y bar 211, --.

### COLUMN 10:

Line 49, "arc" should read -- are --.

### COLUMN 12:

Line 32, "slider" should read -- the X-Y slider --.

### COLUMN 13:

Line 11, "comprising" should read -- comprising: --.

### COLUMN 14:

Line 24, "first direction" should read -- first-direction --. Line 25, "first direction" should read -- first-direction --.

MAILING ADDRESS OF SENDER:

PATENT NO. <u>6,946,757 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile
FORM PTO 1050 (REV. 3.82)

No. of add'l. copies @ 30¢ per page

